

Annexure D

BUILDING SAFETY CERTIFICATE

No.-

Dated :-

It is Certified that the existing buildings **MIS INTERNATIONAL SCHOOL** (Name of the building or premises) at Survey No- 33/1 Opposite Chatrapati Sports Complex, Balewadi, Pune-45 is having as per details below.

Detail of Block(s) in School	Block (1)	Block (2)
No. of Floor(s) in the Block	G + 6	LGF + UGF + 6

These buildings are owned/occupied by **MIS INTERNATIONAL SCHOOL** have complied with the Building safety requirements and verified by the officers concerned of **Public Works Department Pune** on- **29/09/2025** in the presence of **Ms. Monika Chhabra, Principal MIS International School** and that the building/premises is fit for occupancy for running school with effect from- **30/09/2025** to **30/09/2026** in accordance with rule and subject to compliance of the specific conditions as appended.

Nishikant Payal
(Nishikant Payal)

Deputy Engineer

P.W. Rajbhavan Sub Division
Pune 411007

Dr Surendrakumar Katkar
(Dr Surendrakumar Katkar)
Executive Engineer
Public Work Division
Pune 411001



Issued on / /2025 at Pune by.
Ow.no. DB /NOC/ **7890** / 2025
Office of the Executive Engineer
Pune Public Work Division Pune
Date : - **1 OCT 2025**

Copy to :- Deputy Engineer , P. W. Rajbhavan Subdivision , Pune 411007
Copy to :- The Principal **MIS INTERNATIONAL SCHOOL** (Name of the building or premises) at Survey No- 33/1 Opposite Chatrapati Sports Complex, Balewadi, Pune-45 For Information vide your letter. Dated :- 13/08/2025